MIN

VARIANT



DESCRIPTION

Tin bronze alloy solid rod

Solid wire rod recommended for high strength welds on phosphor bronze materials. Weld deposits have high tensile and yield strengths and greater hardness due to the 7 to 9 percent tin content. It is used as an overlay on cast iron or steel, to join dissimilar metals, for maintenance repair and fabrication of valve bodies, seats, bearings, bushings, gears, propellers, impeller blades and housings. Preheat is recommended. It is recommended for joining welding of with Cu-Sn alloy. Best for the joining welding of Cu-Zn alloy with steel.

SPECIFICATIONS

A-No (QW442)

ISO	-	AWS A5.7	ERCuSn-C
DIN 1733	SG-CuSn6 mod.	Werkstoff Number	-
Certifications	-	Shielding	I1
Positions	PA, PB, PC, PD, PE, PF	Current	DC-

ASME QUALIFICATIONS		FERRITE	PREN	HARDNESS
F-No (QW432)	33	-	-	90HB

MECHANICAL PROPERTIES

CHEM. COMP. %	DEFAULT
Mn	0.25
Al	0.001
Sn	8
Р	0.01
Si	0.1
Fe	0.01
Zn	0.01
Pb	0.01

Tensile strength R _m MPa	380	380
Yield strength R _{p0.2} MPa	-	130
Elongation A (L ₀ =5d ₀) %	0	25
Impact Charpy ISO-V	-	-
Impact Charpy ISO-V	-	-
WELDING PARAMETERS	1.6 mm	2.4 mm
Ampere	110A - 150A	175A - 250A
Voltage	-	-
Packaging	Ø 1,6÷4,0 mm	Ø 1,6÷4,0 mm
Packaging Type	5kg carton tube	5kg carton tube



APPLICATION

Used for welding various copper-based alloys to themselves, CMn steels, or cast irons, and for repairing and joining castings, this consumable is also suitable for weld surfacing to provide a bearing surface and/or corrosion-resistant overlay on steel components, shafts, etc. Avoiding stainless steels is recommended due to chromium pick-up causing embrittlement. The tin bronze weld metal can be sluggish due to its wide melting range. Preheating to approximately 200°C can enhance fluidity when dealing with thick sections. To prevent hot cracking, it's advisable to maintain the interpass temperature below 200°C. This consumable is also applicable for welding copper materials if the presence of tin in the weld metal is acceptable, such as in copper and tin bronzes, particularly for joining copper-zinc alloys and steels. For multi-layer welding on steel, pulsed arc welding is advised, and it is also suitable for oven soldering.

ALLOY TYPE

Tin bronze alloy wire for welding similar tin bronze (phosphor bronze) alloys.

MICROSTRUCTURE

A multi phase copper base structure with complex eutectoids.

Tin bronze up to 10%Sn+0.5%P. Cu + 20-25%Sn. Cu + 40%Zn, manganese bronze.